

FOR IMMEDIATE RELEASE

DW Spectrum™ IP VMS v2.3.0.8388 Release Notes

Bug Fixes

- Some Axis cameras working on software version 2.2 cannot be added to 2.3 — fixed.
- If Axis cams were added manually to the multi-server system and auto discovery is off all the time, the cameras could lose the stream after moving between servers — fixed.
- In case cameras were auto discovered but later multicast was turned off, cameras did not go online after the server restarted automatically — fixed.
- If NAS is mounted to the system based on Windows Server 2008 PS with interior authentication, major memory leak was detected — fixed.
- Some cameras lost the secondary stream within the software because of improper OnVIF replying — worked around at the software side.

For auto-updates, please use the following password: 8388:tfk4af