



Everything's Digital



OMNI-PLUS (Infinity)

IR Remote Controller & Motion Setup

 **OMNI-PLUS™**



Step 1: Accessing the Menu

1. Press [KEY] + [ID] (Default is "001" for ID=1)
2. Press [ENT] to access the Menu

Note: the camera id is three digit numbers











Step 2: Activating Motion Alarm




5. MOTION	
	MOTION
	SET WINDOW
	ALL SET
	ALL CLEAR
	SENSITI
	SHOW INDI
	DELAY OUT

1. Go to Motion Menu
2. Set Motion to "ON"
3. Click [Set Windows] and set your area of detection
4. Press the Left arrow button until you exit back to the Motion Menu
5. Zoom out to the farthest you want the camera to zoom out and press [7](Wide)
6. Zoom in to the farthest you want the camera to zoom in and press [8](Tele)
7. Click [Exit Jump] then click [Save & Exit]
8. Once you are out of the menu press [9](ON/OFF) to activate motion alarm

OMNI-PLUS on Screen Menu Setup

1. EXPOSURE		6. PRIVACY	
	LENS		MASK 1
	E. SHUTTER		MASK 2
	BLC		MASK 3
	MAX_DR		MASK 4
	AGC		MASK 5
	STARLIGHT		MASK 6
2. COLOR		7. SYNC	
	WB MODE		SYNC MODE
	R-Y GAIN		V_PHASE
	B-Y GAIN		
3. DAY&NIGHT		8. SETUP	
	D&N MODE		CAMERA ID
	C-SUP		TITLE
	A-SUP		DPC
			MONITOR
			LANGUAGE
	BAUDRATE		OMNI LENS

OMNI-PLUS on Screen Menu Setup

4. FUNCTION		9. EXIT	
	MIRROR		EXIT
	SHARPNESS		SAVE & EXIT
	GAMMA		FACTORY SET
	FREEZE		
	NEGA		
	3D_DNR		
	D_ZOOM		
	SLC		
	HME		
	DIS		
5. MOTION			
	MOTION		
	SET WINDOW		
	ALL SET		
	ALL CLEAR		
	SENSITI		
	SHOW INDI		
	DELAY OUT		