## **DW-MAX Record Schedule Setup Locally**



(8) To reset the settings to default, click **DEFAULT** 

If you need technical assistant please Call:866-446-3516 option#2

DEFAULT

ESC

## DW-MAX Record Schedule Setup Remotely

(2) Select a Site and click OK

(1) Launch the software and click NETWORK SETUP



N	TWORK SETUP					8	3
-9	ITE SETUP						
	ADDRESS	LOCATION	PORT #	TYPE	D	REGISTERING SITE	P
	192.108.250.58	Ulgital	12000	th.	- ann	UPDATE	
						DELETE	
							-
2							
							F
						AVE	-
						~	

(5) Click on **CONNECT** 



(3) Enter the password and click LOGIN



## (6) Click on Record Buzzer Interval Record ALARM SETUP 192.168.250.58 IPORT NUMBER I CHANNEL SELECT CAMERA 1 NORMAL OPEN I INPLIT . CONNECT DISCONNECT 4 I DURATION 5 Ver 2. 0. 0. 4 CLOSE



0

(4) Click on BACKUP

If you need technical assistant please Call:866-446-3516 option#2

## DW-MAX Record Schedule Setup Remotely



If you need technical assistant please Call:866-446-3516 option#2