


DW-MAX AVI Save Setup

(1) Load the Software and click **BACKUP VIEWER**



(2) Click **OPEN** and select the "AM4" file from the PC or USB



(3) Select 1-Screen Division and the camera you want to convert to an AVI file (the AVI SAVE button will enable)




(4) Set the **FRAMERATE** and **SIZE**, then click **START**



(5) You will see the Save Progress Bar, once the save is complete a window will open automatically



(6) Double click the file to load it, if the window doesn't show up it's located in "C:\WEB_BACKUP"



If you need technical assistant please Call:866-446-3516 option#2